

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7




FIG.8




FIG.9A
adjustment




FIG.9B
press




FIG.9C
stapler movement




FIG.9D
binding




FIG.10A
adjustment




FIG.10B
bundle feed → binding




FIG.10C
bundle feed → contacting




FIG.10D
folding




FIG.11A




FIG.11B




FIG.12




FIG.13




FIG.14




FIG.15




FIG.16




FIG.17




FIG.18




FIG.19




FIG.20 A

Saddle stitching mode




FIG.20 B




FIG.20 C




FIG.21




FIG.22

Middle folding mode without binding




FIG.23




FIG.24




FIG.25




FIG.26

